



MASK Perimeter Lighting



MASK Overhead Lighting


ABOVE WATER



MASK ALL Lighting




MASK Perimeter Lighting



MASK Overhead Lighting

UNDERWATER



MASK ALL Lighting

6:16 35%

Lux Light Meter

HELP RESET

min	avg	max
0	5	19

14

LUX FC

1.0x

STORE RECALL CALIBRATE

6:15 36%

Lux Light Meter

HELP RESET

min	avg	max
0	4	13

5

LUX FC

1.0x

STORE RECALL CALIBRATE

6:15 36%

Lux Light Meter

HELP RESET

min	avg	max
0	3	10

10

LUX FC

1.0x

STORE RECALL CALIBRATE